



P O Box 33611  
Lusaka

Tel: 260 211 221355/227989  
Fax: 260 211 238181

#### ADDENDUM NO.1

#### ZNCB/RFP/P&F/22/2022: TENDER FOR PROPOSED REFURBISHMENT WORKS AT ZANACO 3<sup>RD</sup> FLOOR OF HEAD OFFICE BUILDING

-----  
Reference is made to the above captioned tender.

Kindly be informed as follows;

No.	Questions from Bidders	Response from Zanaco
1	What are the specifications of the aluminum to be used for partitioning the floor?	Black powder coated aluminum. Specification can be obtained on site.
2	How many sockets need to be worked on in relation to the power poles? Kindly also advise how many poles should a work station have?	Provisional Item. 8 sockets for each pole
3	<ul style="list-style-type: none"> <li>Kindly share the kitchen pictures and room measurements.</li> <li>Kindly share the specifications of the kitchen unit.</li> <li>Will there be any changes in the current room space?</li> </ul>	<ul style="list-style-type: none"> <li>Pictures are attached</li> <li>Length 287mm * 2 (Top and bottom units)</li> <li>No, the room will remain the same.</li> </ul>
4	Are we doing anything to the fire alarm system and air-conditioning units when doing the ceiling works?4	These will need to be worked around. Secure during work and protect them.
5	Clarification on rubber coated carpet tiles. Will this be a mandatory consideration for vendor selection? Others may have an advantage point in terms of price if they quote none rubber carpet tiles?	Strict specification is the rubberized carpet tiles as per ZANACO standard.

6	Will the floor tiles in the toilet rooms and kitchen room be maintained?	Tiles must be replaced.
7	Will there be any concrete alterations?	No concrete alterations.
8	Is the frosting part of the scope for the glass fittings?	No, requirement only includes aluminum and glass fittings.
9	Will Site Visit certificates be provided to those that attended and is it mandatory to attend the site visit?	Not a requirement.
10	Will works be done in a live environment?	Yes, work will be done in a live/active environment.
11	Will there be any works done on the landing bay?	Quote as per BOQ. Inhouse guidance will be provided.

Please note that all other details pertaining to this RFP remain unchanged.

  
Mundia Siyauya

A/HEAD - SUPPLY CHAIN MANAGEMENT